 Tesla, Inc. Service Bulletin		<h2 style="margin: 0;">Inspect Restraint Control Module Configuration</h2>	
SB-22-20-002 April 22, 2022			
Classification		Section/Group	Mobile Service
Recall Bulletin		20 - Safety and Restraint	Can Perform (where permitted)
Model Year	Model	Country/Region	Build Location
2022	Model 3	Europe	Giga Shanghai
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Some Model 3 vehicles may have a restraint control module (RCM) that was not initialized prior to customer delivery. An RCM that is not initialized may prevent passive safety, active safety and chassis control systems from performing as designed.

Correction

Run a diagnostic routine to confirm this condition. If the routine is not successfully completed, create a Toolbox session and escalate the session when additional support is required.

Correction Description	Correction	Time
Inspect Restraint Control Module Configuration; Inspection Passed	S012220002	0.05
Inspect Restraint Control Module Configuration; Inspection Failed	S022220002	0.05

Procedure

1. Connect a laptop with Toolbox 3 to the vehicle.
2. Select the **Actions** tab, and then search for "ODIN_M3_RCM_retrofit" (Figure 1).




Figure 1

3. Select **ODIN M3 RCM retrofit**, and then click **Run Network** (Figure 2). Allow the routine to complete before continuing.




Figure 2

4. Examine the result after the routine has completed.
 - If the result shows [PASS] (Figure 3), go to step 6.



Figure 3

- If the result shows [FAIL] (Figure 4), go to the next step.



Figure 4

5. Create a toolbox session, using Toolbox article [6001900, ODIN M3 Retrofit RCM Service fails](#) as a starting point. Diagnose the problem. If you require additional support, escalate the session.
6. Disconnect the laptop from the vehicle.