



# Repairing Pick Up Holes

<b>Classification</b>	Campaign Bulletin	<b>Section/Group</b>	10 - Body	<b>Country/Region</b>	Europe
<b>Year</b>	2015	<b>Model</b>	Model S	<b>Version</b>	All

**Bulletin Classification:** *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

## Condition

Some Model S vehicles might have minor damage to one or more of the pick up holes on the underside of the Sill.

## Correction

Send the vehicle to a Tesla Approved Body Shop and have them perform the procedure in BR-16-10-001, "Pick Up Hole Repairs".

Correction Description	Correction	Time
Repair Pick Up Hole(s) (Sublet to Tesla Approved Body Shop)	S011610001	0.0

**Affected VIN(s)** This information is for reference purposes only. This list is not intended to be the sole information source for updates.

5YJSA7E15FF108656  
 5YJSA7E28FF110894  
 5YJSA7E25FF104308  
 5YJSA7E29FF107745

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@teslamotors.com](mailto:ServiceBulletinFeedback@teslamotors.com).