



Replace Trunk Lid

Classification Campaign Bulletin **Section/Group** 10 - Body **Country/Region** United States

Year 2017 **Model** Model 3 **Version** All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Some Model 3 vehicles might have a crack in the trunk lid paint, that might allow water entry.

Correction

Replace the trunk lid.

Correction Description	Correction	Time
SB-17-10-004 Not Applicable	S011710004	0.00
Replace Trunk Lid	S021710004	0.60

Required Part(s):	Part Number	Description	Quantity
	1081460-E0-B	TRUNK ASSY, MODEL 3, E-COATED	1
These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.			

Procedure

Replace the trunk lid (refer to Service Manual procedure 10107002).

Affected VIN(s) Affected Model 3 vehicles built before approximately August 2, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.