



Replace Sunvisors Due to Misprinted Labels, Canada

Classification	Campaign Bulletin	Section/Group	15 - Interior Trim	Country/Region	Canada
Year	2016	Model	Model X	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

This Service Bulletin supersedes SB-17-15-008, dated 2-Nov-17. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Some Canada-market Model X vehicles have sunvisors with misprinted labels.

Correction

Check the labels on the sunvisors. Replace the sunvisor(s), if necessary.

Correction Description	Correction	Time
Vehicle Inspection Only; Sun Visor Replacement Not Required	S011715008	0.05
Replace LH Sun Visor Due To Misprinted Label	S021715008	0.20
Replace RH Sun Visor Due To Misprinted Label	S031715008	0.20
Replace LH and RH Sun Visors Due To Misprinted Labels	S041715008	0.40

Required Part(s):	Part Number	Description	Quantity
		If required, one of the following:	
	1084040-51-F	ASY SUNVISOR LH PROV FOG CA	1
	1084040-52-F	ASY SUNVISOR LH PROV BLACK CA	1
	1084040-53-F	ASY SUNVISOR LH ALCANTARA FOG CA	1
	1084040-54-F	ASY SUNVISOR LH ALCANTARA BLACK CA	1
		If required, one of the following:	
	1084041-51-F	ASY SUNVISOR RH PROV FOG CA	1
	1084041-52-F	ASY SUNVISOR RH PROV BLACK CA	1
	1084041-53-F	ASY SUNVISOR RH ALCANTARA FOG CA	1
	1084041-54-F	ASY SUNVISOR RH ALCANTARA BLACK CA	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

- Inspect the LH and RH sunvisors (Figure 1).
 - If either visor label has “Warning Avertissement” (with a missing "E") printed on it, replace the affected visor(s) (refer to Service Manual procedure 15051002).

NOTE: Revision -G visors are slightly different in appearance than earlier versions. If installing a revision -G visor, replace both the LH and RH visors.
 - If both visor labels have “Warning Avertissement” printed on them, no further work is required.



Figure 1

Affected VIN(s) Affected Canadian Model X vehicles built between approximately May 20, 2016 and June 16, 2016.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.