



Replace Front Passenger Air Bag

Classification	Recall Bulletin	Section/Group	20 - Safety and Restraint	Country/Region	United States, Canada
Year	2012	Model	Model S	Version	All

Bulletin Classification: *This Recall bulletin must be applied to all vehicles listed below. Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers only. Work must be logged and tracked by Tesla Service. Any work carried out by uncertified technicians on this issue may not be appropriately performed or recorded and could lead to an unsafe condition and/or void warranty provisions.*

This Service Document supersedes SB-17-20-001 R1, dated 13-Sep-17. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

The propellant in the front passenger air bag inflator may degrade over time, which could cause the inflator body to rupture in the event the air bag is deployed.

Correction

Replace the front passenger air bag with an updated part.

Required Part(s):	Part Number	Description	Quantity
		Use one of the following:	
	1118926-00-A	MS NA - PASSENGER AIRBAG CAMPAIGN KIT	1
	1005256-00-E	PASSENGER AIRBAG ASSY	1
		If necessary:	
	1004397-10-P	ASY, TOP PAD IP CMPLT, 12A PUR/PUR BLK	1
	1004397-11-P	ASY, TOP PAD IP CMPLT, 12A PUR/ALC BLK	1
	1007818-00-B	ERGO CLIP, 2.5-3 PNL,12W,16L,169 COATING	1-9

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
Replace Front Passenger Air Bag, 2012 Model S	S011720001	0.50

Procedure

1. Replace the front passenger air bag (refer to Service Manual procedure 20010302).

Affected VIN(s) Affected 2012 Model S vehicles sold in the United States and Canada built before approximately January 18, 2013.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.