



## Replace Discolored Pinwheel Caps

<b>Classification</b>	Repair Bulletin	<b>Section/Group</b>	34 - Wheels & Tires	<b>Country/Region</b>	United States, Canada
<b>Year</b>	2018	<b>Model</b>	Model 3	<b>Version</b>	All

**Bulletin Classification:** This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

### Condition

Certain Model 3 vehicles were delivered with 18 inch pinwheel caps (aero wheel covers) that have minor discoloration.

### Correction

Upon customer complaint, or when replacing 1 to 3 pinwheel caps, replace all 4 pinwheel caps.

Correction Description	Correction	Time
SB-18-34-002 Not Applicable	S011834002	0.00
Replace Pinwheel Caps	S021834002	0.05

Required Part(s):	Part Number	Description	Quantity
	1044231-00-B	18 INCH PINWHEEL CAP	4

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

### Procedure

Replace all four pinwheel caps (refer to Service Manual procedure 34015021).

**Affected VIN(s)** Affected Model 3 vehicles built between approximately June 29<sup>th</sup>, 2018 and June 30<sup>th</sup>, 2018.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@tesla.com](mailto:ServiceBulletinFeedback@tesla.com).