



# Replace Front Passenger Airbag

<b>Classification</b>	Recall Bulletin	<b>Section/Group</b>	20 - Safety and Restraint	<b>Country/Region</b>	China, Japan, Macau, Taiwan
<b>Year</b>	2014 - 2016	<b>Model</b>	Model S	<b>Version</b>	All

**Bulletin Classification:** *This Recall bulletin must be applied to all vehicles listed below. Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers only. Work must be logged and tracked by Tesla Service. Any work carried out by uncertified technicians on this issue may not be appropriately performed or recorded and could lead to an unsafe condition and/or void warranty provisions.*

*This Service Bulletin supersedes SB-19-20-001, dated 2-Apr-19. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.*

## Condition

The propellant in the front passenger airbag inflator might degrade over time, which could cause the inflator body to rupture in the event the airbag is deployed.

## Correction

Replace the front passenger airbag with an updated part.

Correction Description	Correction	Time
Replace Front Passenger Airbag, 2014 - 2016 Model S, China, Japan, Macau, And Taiwan	S011920002	0.5

Required Part(s):	Part Number	Description	Quantity
	1463363-99-B	MS EU-APAC - PASSENGER AIRBAG ASSY (PAB) CAMPAIGN	1
		<b>Hongkong only:</b>	
	1463363-99-A	MS EU-APAC - PASSENGER AIRBAG ASSY (PAB) CAMPAIGN	1
		<b>OR</b>	
	1463363-99-B	MS EU-APAC - PASSENGER AIRBAG ASSY (PAB) CAMPAIGN	1
		<b>OR</b>	
	1463363-00-B	MS EU-APAC - PASSENGER AIRBAG ASSY (PAB) CAMPAIGN	1
		<b>If necessary:</b>	
		Left Hand Drive (LHD) vehicles:	
	1004397-10-P	ASY, TOP PAD IP CMPLT, 12A PUR/PUR BLK	1-9
	1004397-11-P	ASY, TOP PAD IP CMPLT, 12A PUR/ALC BLK	
	1007818-00-B	ERGO CLIP, 2.5-3 PNL,12W,16L,169 COATING	
		Right Hand Drive (RHD) vehicles:	
	1023232-10-M	ASY TOP PAD RHD, 12A PUR/PUR BLK RHD	1
	1023232-11-M	ASY TOP PAD RHD, 12A PUR/ALC BLK RHD	1
	1007818-00-B	ERGO CLIP, 2.5-3 PNL,12W,16L,169 COATING	1-9

This part number was current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

## Procedure

Replace the front passenger airbag (refer to Service Manual procedure 20010302).

**Affected VIN(s)** Affected 2014, 2015, and 2016 China, Japan, Macau, and Taiwan Model S vehicles that had the front passenger airbag installed in the factory prior to approximately December 5, 2016.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@tesla.com](mailto:ServiceBulletinFeedback@tesla.com).