

 Tesla, Inc. Service Bulletin		<h2>Provide Aero Wheel Cap Set</h2>	
SB-19-90-004 December 20, 2019		R1	
Classification Parts and Accessories Bulletin		Section/Group 90 - Accessories	Mobile Service Can Perform (where permitted)
Model Year 2019	Model Model 3	Country/Region Europe	Version All
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Parts and Accessories Bulletin: This bulletin provides instructions for a procedure that is not the result of a defect.

This Service Document supersedes SB-19-90-004, dated 5-Dec-19. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Some European customers who ordered the original Model 3 18 inch Winter Wheel and Tire Package did not receive the Aero Wheel Cap set that was supposed to be included with the package.

Correction

Upon customer complaint, provide an Aero Wheel Cap set to the customer.

Correction Description	Correction	Time
SB-19-90-004 Not Applicable	S011990004	0.00
Provide Aero Wheel Cap Set	S021990004	0.05

Part Number	Description	Quantity
Parts Required 1044231-99-B	18 INCH AERO WHEEL CAP	4

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

Upon customer complaint, provide an Aero Wheel Cap set to the customer.



NOTE: Use the "Customer Pre-Pay" paytype to close out the Repair Order.