

 Tesla, Inc. Service Bulletin		<h2>Replace Car Computer Affecting Rear Facing Camera Functionality</h2>	
SB-20-21-001 March 9, 2020			
Classification Campaign Bulletin		Section/Group 21 - Infotainment	Mobile Service Cannot Perform
Model Year 2020	Model Model 3	Country/Region United States	Version All
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Campaign Bulletin: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN list.

Condition

On certain Model 3 vehicles, the image from the rear facing camera might not be displayed on the touchscreen.

Correction

Replace the car computer.

Correction Description	Correction	Time
SB-20-21-001 Not Applicable	S012021001	0.0
Replaced Car Computer Affecting Rear Facing Camera Functionality	S022021001	0.9

	Part Number	Description	Quantity
Parts Required	1462554-S0-I	TLA,CAR.COMP,NA,HW3.0,M3 - PROVISIONED	1
	2007104-00-B	NUT,HF,M8x1.25,[10] G1409,LOCK	4
	1116594-00-B	BOLT,EHS,M6x19,[88],ZN,SMAT,ADH	4
<small>These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.</small>			
Special Tools	1504492-00-A	M3 Car Computer Coolant Plug (2)	
	1108272-00-B	Cap, Logic Conn, Inv, 3DU	
Shop Supplies	Absorbent material		

Procedure

Replace the car computer (refer to Service Manual procedure 21151002).