

 Tesla, Inc. Service Bulletin		<h2>Replace Driver Airbag</h2>	
SB-21-20-007 November 10, 2021			
Classification Recall Bulletin		Section/Group 20 - Safety and Restraint	Mobile Service Can Perform (where permitted)
Model Year 2021	Model Model S, Model X	Country/Region United States, Canada	Version Palladium
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Model S and Model X vehicles were equipped with driver airbags that do not meet internal quality standards.

Correction

Replace the driver airbag.

Correction Description	Correction	Time
Replace Driver Airbag	S01212007	0.05

Part Number	Description	Quantity
Parts Required 1625769-73-D	MSX P2 - DRIVER AIRBAG ASSEMBLY	1
<small>This part number was current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.</small>		

Procedure

Replace the driver airbag (refer to Service Manual procedure 20010102; [Model S](#), [Model X](#)).