TESLA	Tesla, Ir Service Bul		Replace Front Row Curtain Airbags			
SB-22-20-003 May 5, 2022			•			
Classification			Section/Group	Mobile Service	Configuration	
Recall Bulletin			20 - Safety and Restraint	Can Perform (where permitted)	All	
Model Ye	ar Model	(Country/Region	Build Location	Build Location	
2021 - 202	2 Model X	١	North America	Fremont	Fremont	
	nd model year(s) listed this bulletin for a particu		approximation of the affected VIN list. Re	fer to the VIN/Bulletin Tracker or Custo	mer/Vehicle profile to determine	

Recall Bulletin: Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

On certain Model X vehicles, when the LH or RH side front row window is lowered, the corresponding LH or RH side front row curtain airbag may not reach the intended position upon full deployment. This may cause the curtain airbag performance to not comply with regulatory requirements.

Correction

Replace the LH and RH front row curtain airbags with revision H or later.

Correction Description	Correction	Time
Replace LH And RH Front Row Curtain Airbags	S012220003	1.10

	Part Number	Description	Quantity
Parts Required	1036756-00-H	1ST ROW CURTAIN AIRBAG - LEFT HAND	1
	1036759-00-H	1ST ROW CURTAIN AIRBAG - RIGHT HAND	1
	1004400-00-A	NUT,HEX,M8-1.25,STL,ZN,PATCH, W/WSHR	2

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.

Procedure

Replace the LH and RH front row curtain airbags (refer to Service Manual procedure 20010502).