



Front Hoodliner Upgrade

Classification	Repair Bulletin	Section/Group	10 - Body	Country/Region	North America
Year	2012	Model	Model S	Version	All

Bulletin Classification: This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

This Service Bulletin supersedes SB-13-10-002 R1, dated 14-Oct-14. Each content change is marked by a vertical line in the left margin. Discard the previous version and replace it with this one.

Condition

Water ingress inside frunk area.

Correction

Upon customer complaint, install an upgraded front hoodliner for improved sealing.

Required Part(s):	Part Number	Description	Quantity
	6008003-00-B	HOODLINER, FRONT, ASY	1
	1009399-00-A	BRUSH CLIP 5MM - 22.20MM	14

These part numbers were current at the time of publication. Use the revision listed or later, unless otherwise specified in the Parts Manual.

Correction Description	Correction	Time
Replacement of Front Hoodliner	S011310002	0.7
Inspection Only; Front Hoodliner Replacement Not Required	S021310002	0.0

Procedure

1. Remove the front hoodliner (refer to Service Manual procedure 11104002).

NOTE: The acoustic panel does not need to be removed.

2. Install the updated front hoodliner.

Affected VIN(s) This information is for reference purposes only. This list is not intended to be the sole information source for updates.

5YJSA1DP8CFF00001 - 5YJSA1DP0CFF00042
5YJSA1DP6CFP01201 - 5YJSA1DP5CFP01208
5YJSA1AP7CFR00102 - 5YJSA1AP9CFR00117
5YJSA1DP2CFS00001 - 5YJSA1DP5CFS00025

For feedback on the accuracy of this document, email ServiceBulletinFeedback@teslamotors.com.

