



# Wall Connector Cable Organizer Upgrade, APAC

<b>Classification</b>	Parts and Accessories Bulletin	<b>Section/Group</b>	50 - External Charging Connectors	<b>Country/Region</b>	Asia Pacific
<b>Year</b>	2013-2015	<b>Model</b>	Model S	<b>Version</b>	All

**Bulletin Classification:** This bulletin provides instructions and guidelines for a vehicle procedure that is not the result of a defect. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

## Condition

Some customers in China, Australia, and Hong Kong received a North American wall connector, which has a cable organizer that does not properly retain the charge handle.

## Correction

Upon customer complaint, provide the customer the correct version of the cable organizer.

**NOTE:** Customers install the cable organizer themselves. No technician work is required.

Correction Description	Correction	Time
SB-15-50-004 Not Applicable	S011550004	0.0
Provide Upgraded Cable Organizer, APAC	S021550004	0.1

Required Part(s):	Part Number	Description	Quantity
	1067116-00-A	DOCK,VEHICLE CONN,EU,NON TSLA	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

**Affected VIN(s)** Affected Model S vehicles in China, Hong Kong, and Australia built before approximately October 14, 2015.

**NOTE:** This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email [ServiceBulletinFeedback@teslamotors.com](mailto:ServiceBulletinFeedback@teslamotors.com).