



Replace Taillights

Classification Campaign Bulletin **Section/Group** 17 - Electrical **Country/Region** All

Year 2017 **Model** Model 3 **Version** All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

On some Model 3 vehicles, the taillights are susceptible to condensation, which affect their appearance, but not their functionality.

Correction

Replace the LH and RH taillights.

Correction Description	Correction	Time
SB-17-17-006 Not Applicable	S011717006	0.00
Replace LH And RH Taillights Due To Condensation	S021717006	0.45

Required Part(s):	Part Number	Description	Quantity
	1077397-00-E	LAMP ASY, REAR BODYSIDE SAE, LH	1
	1077398-00-E	LAMP ASY, REAR BODYSIDE SAE, RH	1
	1077401-00-D	LAMP ASY, LIFTGATE SAE, LH	1
	1077402-00-D	LAMP ASY, LIFTGATE SAE, RH	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

1. Replace the LH and RH taillights (refer to Service Manual procedure 17402001).

Affected VIN(s) Affected Model 3 vehicles built before approximately August 20, 2017.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.

