

 Tesla, Inc. Service Bulletin		<h2>Replace Driver and Front Passenger Knee Airbag Covers</h2>	
SB-21-14-001 August 12, 2021			
Classification		Section/Group	Mobile Service
Campaign Bulletin		14 - Instrument Panel & Pedals	Can Perform (where permitted)
Model Year	Model	Country/Region	Version
2021	Model S	United States	Palladium
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Campaign Bulletin: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN list.

Condition

On certain Model S Palladium vehicles, an improved version of the driver and front passenger knee airbag covers is available.

 **NOTE:** The functionality and safety of the factory-installed knee airbags and covers are not affected.

Correction

Replace the driver and front passenger knee airbag covers with updated parts.

Correction Description	Correction	Time
Replace Driver And Front Passenger Knee Airbag Covers With Updated Parts	S012114001	0.5

Part Number	Description	Quantity
Parts Required 1582859-00-E	IP, LHD, LH, KAB COVER, ASY	1
1563013-00-E	IP, LHD, RH KAB COVER, ASY	1
1116594-00-B	BOLT,EHS,M6x19,[88],ZN,SMAT,ADH	16

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

1. Replace the driver knee airbag cover (refer to Service Manual procedure [14056002](#)).
2. Replace the front passenger knee airbag cover (refer to Service Manual procedure [14056102](#)).