Subject: KX-TD816/1232 EPROM Version Upgrade

Document Number: KXTD1232005

Current System	Upgrade To	Required
KX-TD1232*	KX-TD1232-1	Software E-Proms Only.
KX-TD1232	KX-TD1232-2	Software E-Proms and CPU.
KX-TD1232	KX-TD1232-3	Software E-Proms and CPU.
KX-TD1232-1	KX-TD1232-2	Software E-Proms and CPU.
KX-TD1232-1	KX-TD1232-3	Software E-Proms and CPU.
KX-TD1232-2	KX-TD1232-3	Software E-Proms Only.
KX-TD816	KX-TD816-1	Software E-Proms Only.
KX-TD816	KX-TD816-2	No Upgrade Possible.
KX-TD816	KX-TD816-3	No Upgrade Possible.
KX-TD816-1	KX-TD816-2	No Upgrade Possible.
KX-TD816-1	KX-TD816-3	No Upgrade Possible.
KX-TD816-2**	KX-TD816-3	Software E-Proms Only.

* Systems with the following serial numbers require Service Center modification.
Contact the Service Center for Availability and Pricing.
3xIAxxxxxx (PC Board Modification)
4AIAxxxxxx (PC Board Modification)
4BIAxxxxxx (PC Board Modification)
4CIA000000 to 4CIA000214 (PC Board Modification)
4Jxxxxxxxx (Soldered in SRAM)
4Kxxxxxxxx (Soldered in SRAM)
4Lxxxxxxxx (Soldered in SRAM)
5Axxxxxxxx (Soldered in SRAM)
5Bxxxxxxxx (Soldered in SRAM)

** Systems with a serial number suffix of "C" Can Not be upgraded.
xxxxCxxxxxx (example 8BAIC015300) The units shipped Aug 96 to Jan 98.