



Premium Center Console Upgrade

Classification	Campaign Bulletin	Section/Group	14 - Instrument Panel & Pedals	Country/Region	North America
Year	2012-2013	Model	Model S	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electricity repairs, and should only be executed by trained professionals. Tesla Motors assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Upgraded premium center consoles are now available.

Correction

Remove the existing revision A premium center console, and install the revision B part.

NOTE: Piano Black is the only finish package available at this time. This bulletin will be revised once additional finish packages are available.

Required Part(s):	Part Number	Description	Quantity
	1032316-02-B	ASSEMBLY, DROP IN CONSOLE, PIANO BLACK	1
	1020856-00-A	A-PILLAR UPPER STANDOFF, FOAM NEOPRENE	2
		Shop supplies	
		Painter's tape	
		If necessary, choose the correct variation:	
	1033417-00-A	DOCK CONNECTOR KIT, APPLE LIGHTNING	1
	1033417-02-A	DOCK CONNECTOR KIT, MICRO USB	1

Correction Description	Correction	Time
Vehicle Inspection Only; Upgraded Premium Center Console Not Required	S011415004	0.1
Customer Declines Premium Center Console Replacement	S021415004	0.1
Replace Premium Center Console	S031415004	0.35
Replace Premium Center Console, Install Phone Adaptor Kit	S041415004	0.45
Replace Premium Center Console, Assemble 4 Movable Dividers	S051415004	0.4
Replace Premium Center Console, Assemble 4 Movable Dividers, Install Phone Adaptor Kit	S061415004	0.5

Procedure

1. Remove the premium center console (refer to Service Manual procedure 15192602).

NOTE: Do not remove the mounting bracket from the vehicle. It is reused for the revision B center console.

2. Verify the replacement center console is revision B.

3. Install the center console and any phone dock connector kit necessary (refer to SB-13-14-014, "Premium Center Console Installation").

4. Pack the revision A console securely into the packaging that the revision B console was shipped in.

5. Ship the revision A console to the Fremont Factory:

Tesla Motors West Ramp
c/o James Chen - Service
45500 Fremont Blvd.
Fremont, CA 94538 USA

Affected VIN(s) This information is for reference purposes only. This list is not intended to be the sole information source for updates.

5YJSA1DP4DFP01831
5YJSA1CG3DFP03670
5YJSA1DP7DFP05677
5YJSA1CNXDFP05768
5YJSA1DP2DFP06297
5YJSA1CN7DFP08224
5YJSA1CG5DFP08322
5YJSA1DG8DFP08491
5YJSA1DG0DFP09554
5YJSA1DN7DFP16256
5YJSA1CN5DFP26480

For feedback on the accuracy of this document, email ServiceBulletinFeedback@teslamotors.com.